

IN THIS REPORT: run[ 0003; Brandon Hospital Clean Utilities, [YES], This run is for the Clean Utilities only so that we can clear the Plumbers! Line#1078,Part#107108,Elv# 53 ]

<u>Width</u>	<u>Length</u>	<u>Qty</u>	<u>Waste Area</u>	<u>Waste Cost</u>	<u>Yield Area</u>	<u>Yield Cost</u>	<u>Total Area</u>	<u>Total Cost</u>
<b>1/2" Partical Board Mel/Mel - WA 1570 White - WA 1570 White</b>								
49.0	97.0	3	20.64	9.288	76.11	34.250	96.75	43.538
<b>Subtotals</b>			<b>20.64</b>	<b>9.29</b>	<b>76.11</b>	<b>34.25</b>	<b>96.75</b>	<b>43.54</b>
<b>1/4" MDF HPL/HDO - WA 7205 Bengal Teak -</b>								
49.0	97.0	12	67.03	50.270	322.99	242.246	390.02	292.516
<b>Subtotals</b>			<b>67.03</b>	<b>50.27</b>	<b>322.99</b>	<b>242.25</b>	<b>390.02</b>	<b>292.52</b>
<b>1/4" MDF Raw/Raw - WA 1570 White -</b>								
49.0	97.0	3	20.08	4.819	77.43	18.583	97.51	23.401
<b>Subtotals</b>			<b>20.08</b>	<b>4.82</b>	<b>77.43</b>	<b>18.58</b>	<b>97.51</b>	<b>23.40</b>
<b>1/4" MDF Vinyl/Raw - WA 1570 White -</b>								
					<b>16.25</b>	<b>4.875</b>	<b>16.25</b>	<b>4.875</b>
49.0	97.0	16	145.53	49.479	374.50	127.330	520.03	176.809
<b>Subtotals</b>			<b>145.53</b>	<b>49.48</b>	<b>390.75</b>	<b>132.20</b>	<b>536.28</b>	<b>181.68</b>
<b>11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White</b>								
					<b>12.58</b>	<b>16.985</b>	<b>12.58</b>	<b>16.985</b>
49.0	97.0	26	71.81	89.758	760.19	950.242	832.00	1040.000
<b>Subtotals</b>			<b>71.81</b>	<b>89.76</b>	<b>772.78</b>	<b>967.23</b>	<b>844.58</b>	<b>1056.99</b>
<b>11/16" Particle Board HPL/HPL - WA 7205 Bengal Teak - WA 7205 Bengal Teak</b>								
49.0	97.0	5	19.14	25.841	140.86	190.159	160.00	216.000
<b>Subtotals</b>			<b>19.14</b>	<b>25.84</b>	<b>140.86</b>	<b>190.16</b>	<b>160.00</b>	<b>216.00</b>
<b>3/4" Particle Board Mela/Mela - WA 1570 White - WA 1570 White</b>								
					<b>38.38</b>	<b>24.948</b>	<b>38.38</b>	<b>24.948</b>
49.0	97.0	31	75.93	56.945	923.84	692.878	999.76	749.823
49.0	109.0	5	8.15	6.520	173.21	138.566	181.36	145.085
61.0	97.0	8	17.95	13.824	304.22	234.247	322.17	248.071
<b>Subtotals</b>			<b>102.03</b>	<b>77.29</b>	<b>1439.64</b>	<b>1090.64</b>	<b>1541.67</b>	<b>1167.93</b>
<b>3/4" Particle Board Raw/Raw - -</b>								
					<b>9.96</b>	<b>3.187</b>	<b>9.96</b>	<b>3.187</b>

**Layups**

9/19/01 10:19:58

page 2 of 2

IN THIS REPORT: run[ 0003; Brandon Hospital Clean Utilities, [YES], This run is for the Clean Utilities only so that we can clear the Plumbers! Line#1078,Part#107\_108,Elv# 53 ]

<u>Width</u>	<u>Length</u>	<u>Qty</u>	<u>Waste Area</u>	<u>Waste Cost</u>	<u>Yield Area</u>	<u>Yield Cost</u>	<u>Total Area</u>	<u>Total Cost</u>
<b>3/4" Particle Board Raw/Raw - -</b>								
49.0	97.0	8	49.03	15.691	210.98	67.513	260.01	83.204
<b>Subtotals</b>			<b>49.03</b>	<b>15.69</b>	<b>220.94</b>	<b>70.70</b>	<b>269.97</b>	<b>86.39</b>
<b>Grand Totals</b>			<b>495.28</b>	<b>322.43</b>	<b>3441.50</b>	<b>2746.01</b>	<b>3936.78</b>	<b>3068.44</b>