

6235 Brandon Memorial Hospital, BLDG C NORTH, FLOOR 1, Rm 100 Clean U  
P# 317; BSCRIBE 85; SCRIBE-B  
X= 1 X1= X2= =15/1  
L= 30 1/2 L1= L2=  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C NORTH, FLOOR 1, Rm 111 Clean U  
P# 317; BSCRIBE 85; SCRIBE-B  
X= 1 X1= X2= =15/1  
L= 30 1/2 L1= L2=  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C SOUTH, FLOOR 1, Rm 111 Clean U  
P# 352; DRAWER FRONT, 4EQ 92; DV1040B-4E  
X= 23 19/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 6 29/64 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C SOUTH, FLOOR 1, Rm 111 Clean U  
P# 352; DRAWER FRONT, 4EQ 92; DV1040B-4E  
X= 23 19/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 6 29/64 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C SOUTH, FLOOR 1, Rm 111 Clean U  
P# 352; DRAWER FRONT, 4EQ 92; DV1040B-4E  
X= 23 19/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 6 29/64 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C SOUTH, FLOOR 1, Rm 111 Clean U  
P# 352; DRAWER FRONT, 4EQ 92; DV1040B-4E  
X= 23 19/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 6 29/64 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C SOUTH, FLOOR 1, Rm 100 Clean U  
P# 375; HL WALL DOOR, DBL 96; WB1P00  
X= 16 13/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 17 11/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C SOUTH, FLOOR 1, Rm 111 Clean U  
P# 375; HL WALL DOOR, DBL 96; WB1P00  
X= 16 13/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 17 11/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C SOUTH, FLOOR 2, Rm 200 Clean U  
P# 375; HL WALL DOOR, DBL 96; WB1P00  
X= 16 13/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 17 11/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C SOUTH, FLOOR 2, Rm 211 Clean U  
P# 375; HL WALL DOOR, DBL 96; WB1P00  
X= 16 13/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 17 11/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 1, Rm 100 Clean U  
P# 408; HL BASE FULL HEIGHT, DBL 110; SB1P00  
X= 15 37/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 16 3/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 1, Rm 111 Clean U  
P# 375; HL WALL DOOR, DBL 96; WB1P00  
X= 16 13/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 17 11/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 2, Rm 200 Clean U  
P# 375; HL WALL DOOR, DBL 96; WB1P00  
X= 16 13/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 17 11/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 2, Rm 211 Clean U  
P# 375; HL WALL DOOR, DBL 96; WB1P00  
X= 16 13/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 17 11/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White



6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 3, Rm 300 Clean U  
P# 375; HL WALL DOOR, DBL 96; WB1P00  
X= 16 13/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 17 11/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 3, Rm 311 Clean U  
P# 375; HL WALL DOOR, DBL 96; WB1P00  
X= 16 13/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 17 11/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 1, Rm 100 Clean U  
P# 409; HR BASE FULL HEIGHT, DBL 110; SB1P00  
X= 15 37/64 X1= 3mm Black X2= 3mm Black =15/1  
L= 16 3/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 1, Rm 100 Clean U  
P# 412; DRAWER FRONT, 4EQ 111; DV1040B-4E  
X= 3 61/64 X1= 3mm Black X2= 3mm Black =16/1  
L= 23 19/64 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 1, Rm 100 Clean U  
P# 419; HL WALL DOOR 112; WB1L02  
X= 23 19/64 X1= 3mm Black X2= 3mm Black =16/1  
L= 19 11/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 1, Rm 111 Clean U  
P# 382; HL BASE FULL HEIGHT, SGL 101; BB1L00  
X= 23 19/64 X1= 3mm Black X2= 3mm Black =16/1  
L= 24 3/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 1, Rm 100 Clean U  
P# 412; DRAWER FRONT, 4EQ 111; DV1040B-4E  
X= 3 61/64 X1= 3mm Black X2= 3mm Black =16/1  
L= 23 19/64 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 1, Rm 100 Clean U  
P# 426; HR WALL DOOR 114; WB1R02  
X= 23 19/64 X1= 3mm Black X2= 3mm Black =16/1  
L= 19 11/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C NORTH, FLOOR 1, Rm 111 Clean U  
P# 382; HL BASE FULL HEIGHT, SGL 101; BB1L00  
X= 23 19/64 X1= 3mm Black X2= 3mm Black =16/1  
L= 24 3/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 1, Rm 100 Clean U  
P# 412; DRAWER FRONT, 4EQ 111; DV1040B-4E  
X= 3 61/64 X1= 3mm Black X2= 3mm Black =16/1  
L= 23 19/64 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG B SOUTH, FLOOR 1, Rm 100 Clean U  
P# 404; HL BASE FULL HEIGHT, SGL 109; BB1L00  
X= 23 19/64 X1= 3mm Black X2= 3mm Black =16/1  
L= 16 3/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C NORTH, FLOOR 1, Rm 100 Clean U  
P# 396; HL BASE FULL HEIGHT, SGL 104; BB1L00  
X= 23 19/64 X1= 3mm Black X2= 3mm Black =16/1  
L= 28 3/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C SOUTH, FLOOR 1, Rm 100 Clean U  
P# 336; HR BASE FULL HEIGHT, SGL 88; BB1R00  
X= 23 19/64 X1= 3mm Black X2= 3mm Black =16/1  
L= 26 3/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C SOUTH, FLOOR 2, Rm 200 Clean U  
P# 379; HL BASE FULL HEIGHT, SGL 100; BB1L00  
X= 23 19/64 X1= 3mm Black X2= 3mm Black =16/1  
L= 26 3/16 L1= 3mm Black L2= 3mm Black  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White

6235 Brandon Memorial Hospital, BLDG C SOUTH, FLOOR 3, Rm 300 Clean U  
P# 377; WSCRIBE 97; SCRIBE-W  
X= 1 X1= X2= =16/1  
L= 18 L1= L2=  
11/16" Particle Board HPL/CL - WA 7205 Bengal Teak - WA 1570 White